




Total # of Permits





Total Valuation of Permits














Valuation
Range
between
\$5,000 and
\$150,000

Permit application submittals with a valuation range between \$5,000 and \$150,000 should be able to be completed in-house (vs. sending to an outside plan checker).


Valuation Range: Permits Valued Between \$5,000 & \$150,000







Number of Inspections Performed




<u>Year</u>	<u>Total # of</u> <u>Permits Issued</u>	<u>Valuation</u> (of Issued)	<u>Total # of</u> <u>Permits</u> <u>Submitted</u>	<u>Valuation</u> (of Submitted)	% of Permits Submitted within Valuation Range	% of Internal Plan Checks Completed (or No Review Required) within Valuation Range	Total # of Inspections Performed
2019	727	\$31,033,482	827	\$72,001,032	42%	89%	2092
2020	722	\$32,019,022	726	\$17,516,393	45%	87%	1800
2021	737	\$36,378,610	797	\$77,929,298	52%	86%	1785
2022	797	\$52,958,837	829	\$86,796,787	52%	91%	1824
2023	922	\$90,055,910	952	\$49,587,510	62%	96%	2140

BUILDING DIVISION REVENUE/EXPENDITURES




Code Compliance

Cases by Type		
Building and Permits		
Trees	66	
Nuisance, Storage & Vehicle	99	
Lighting	83	
Trash	76	
Substandard	52	
Snow	43	
Signs	28	
Miscellaneous	56	
Total	719	
Miscellaneous includes: Animal, Camping, Tobacco, Graffiti, Paint, Trespass, BTC/TOT, Addressing, Non Snow ROW, Pool & Spa, Al Fresco, Bed bugs, Mechanical and Fire Code.		



STOP WORK ORDERS






TAG DEFINTIONS


- **RED UNSAFE:** Building damage poses an imminent threat to life or safety
- YELLOW RESTRICTED USE: There is some risk from damage in all or part of the building.
- ORANGE MINOR DAMAGE: A building permit is required for the repair.
- PROPANE: Propane only related hazards.
- **TEMPORARY GREEN SAFE:** The hazard has been temporarily resolved, but a permanent fix is required.
- **GREEN SAFE:** The building has been inspected as safe.

2023 Winter Snow Damage

Overall Statistics

- 850 inspections were performed by Town staff, Mammoth Lakes Fire District, and State resource agencies.
- **680** tags were issued.
- **398** structures were tagged.
- 310 structures received tags for damage.
- 336 public surveys (a report of damage from a member of the public) were submitted.





LEGEND

Red

Yellow

Minor Damage - BP Needed

Propane


Green Temporary

Green Final

<u>Historic</u> = Tag has been changed to a different color, usually to green (i.e. damage has been resolved)

<u>Current</u> = Tag is still applicable. Status may include no building permit submitted, building permitted submitted but not issued, building permit issued but not inspected or finalized.

2023 Winter Snow Damage REPAIR PERMITS



Thank you

For further questions or comments, please contact the Building Division.

